

MANUAL OF LATHE OPERATION

INDEX

	Page	Page	
—A—			
Acme thread	114-115, 143 table	Center rest chuck	182
Aligning tailstock	189	Center tester	75
Allowances for machine fits	225 table	Change gears	26, Part 7
Allowances for reaming	88	Chatter	31
Aluminum, machining	61-63	Check bar	189
Aluminum, drilling	87	Checking trueness of work	70-71, 75
American National screw thread, see National Form thread		Chisel, gouge (woodturning)	203-204
Ameroid, machining	64	Chisel, parting tool (woodturning)	205-207
Angle plate	80	Chisel, skew (woodturning)	204-205
Angular milling cutter	166	Chisel, small gouge (woodturning)	209
Arbor	81, 82	Chisel, small skew (woodturning)	214
Arbor, grinding	172	Chisels, scraping (woodturning)	214
Arbor press	82	Chisel set (woodturning)	200
Areas, calculations	224 table	Chuck, center rest	182
Armature work	180-183	Chuck, drill	83
A. S. M. E. tool bit designations	36	Chuck, headstock	77
Attachments	Part 8	Chuck, independent	74-75
Automatic power feed	22	Chuck, universal	76
—B—			
Back gears	13-14	Chucks, cleaning	79
Bakelite, machining	64	Chucks, removing	77-78
"Bead" (woodturning)	208	Chucks, rules for use	78-79
Bearing, end thrust	10	Circles, calculations	219, 224 tables
Bearings, countershaft	15	Clamping plate, boring	93
Bearings, spindle	9	Clamping plate, milling	168
Bearings, spindle, adjustment	10	Clamp type dog	74
Bearings, spindle, running-in	4	Clearance angles	35
Bearings, Timken	11	Clearance angles, boring	91
Bed construction and care	16-19	Clearance angles, threading	105
Bed, leveling	2	Clutch, line-shaft	197-198
Beetle, machining	64	Coil winding	125-126, 145-154 tables
Belt adjustment	15	Collet attachment	80-81
Belt positions	47	Collet, milling	167-168
Bench top	1	Compound drive lathe, spindle speeds	230
Black walnut (woodturning)	218	Compound gear assembly	98
Block plane (woodturning)	205	Compound rest	20
Boring bar	93	Compound rest handle adjustment	22
Boring operations	90-94	Compound rest, taper work	184-185
Boring tapers	190	Concave cuts (woodturning)	209-210
Boring threads	112-113	Connecting motor	3
Bracket adjustment slot	96	Convex cut (woodturning)	208
Brass, machining	59	Copper, machining	57-60
Brass, drilling	87	Coolants	33
Breaking in lathe	4	Counterbalance, face plate	80
British Standard threads	140 table	Countershaft	14
Bronze, machining	59-60	Countershaft bearings	15
Brown & Sharpe tapers	192-193 table	Countersinking	71-72
Bull gear	13-14	"Cove" cut (woodturning)	209-210
Bushing and sleeve assembly	96, 98	Cross feed handle adjustment	22
—C—			
Caliper, hermaphrodite	69-70	Cross slide	20, 21
Carriage adjustments	20-21	Cross slide stop	165-166
Carriage feeds	122-125, 128-131	Crotch center	88-89
Carriage, removing	21	Cup center	200-201
Carriage stop	164-165	Cut-off operations	160-162
Cast iron, drilling	87	Cut-off operations (woodturning)	211, 212
Cast iron, machining	54	Cutting action	31
Catalin, machining	64	Cutting compounds	50
Celluloid, machining	64	Cutting speeds	49 table
Center gauge	109	—D—	
Center head attachment	70	Decimal equivalents	220-221 table
Centers, lathe	25	Depth of cut	48
Centers, lathe, alignment of	189	Depth of cut, boring	92
Centers, lathe, grinding	180	Depth of cut, threading	48, 110
Center rest	157-159	Depth of thread	104, 135 table
		Dial gauge test	71
		Diamond dresser, grinding	173
		Die castings, drilling	87
		Dividing operations	14
		Dogs, lathe	73, 74

	Page
Double depth of thread	104, 135 table
Double thread screws	104, 120-122
Dovetail slot, milling	167
Draw-in collet attachment	80-81
Drill chuck	83
Drill, countersink	71
Drill gauge attachment	85-86
Drill grinding	85
Drill grinding attachment	86
Drill pad	88-89
Drill set	89-90
Drilling operations	83-90
Drills, lettered	225 table
Drills, numbered	225 table
Drills, twist	83-85, 225 tables

—E—

Electrical coil winding	125-126, 145-154 tables
End mill	166
End mill, grinding	178
End thrust bearing	10
Extension bed for woodturning	200

—F—

Face plate	79-80
Face plate for woodturning	200, 213-215
Facing cuts	44-45
Facing cuts (woodturning)	213-215
Facing tool	44
False cutting edge	32
Feed per spindle revolution	48, 122-125, 128-131 tables
Feed screw handle adjustment	22
Fiber, machining	66
Filing	67
Fine feeds	130-131 table
Finishing cuts	67
Finishing cuts (woodturning)	215-216
Floor legs	2
Fluting	14
Follower rest	159-160
Forged steel parts, machining	54
Form cutting tools	41
Formica gear material, machining	65
Fractional threads	138 table
French polish (wood)	216
French Standard threads	142 table

—G—

Gas engine drive	198
Gear box, reversing	23
Gear bracket positions	96
Gear chart	97
Gear, compound	98
Gear clearance	98
Gear-cutting	171
Gear, idler	98
Gear, spacer	98
Gear train formula	155-156
Gear trains	99-103
Gears, back	13-14
Gears, change	26, Part 7
Gears, threading	26, Part 7
Gibs, adjustment	20-21
Gouge chisel, large	203-204
Gouge chisel, small	209-210
Grinder, bench	37
Grinding lathe centers	180
Grinding operations	171-181
Gum (woodturning)	218

—H—

Half nuts and closing mechanism	24
Handles, adjustment for play	22
Hand rest (woodturning)	200
Hand rest swivel (woodturning)	200
Hard rubber, machining	66
Headstock	5
Headstock chuck	77
Headstock spindle	8
Heat in cutting	33
Heavy cuts	50
Hermaphrodite caliper	69-70
Holding collet set (milling)	167-168
Holding the work	Part 5
between centers	69-84
chucks	74-79
collet attachment	80-81
face plate	79
mandrel or arbor	81-82

—I—

Idler gear	98
Independent chuck	74-75
Indexing mechanism	14
Indexing table	14
Internal grinding	175-176
Internal threads	112-113
International Standard threads	141 table

—J—

Jackshaft	199
Jacobs center rest chuck	182
Jacobs drill chuck	83
Jacobs headstock chuck	77
Joanite, machining	64

—K—

Keys, A. S. A.	170 table
Keyways, standard	170 table
Knurling operations	163-164

—L—

Laminated shims	10
Lathe attachments	Part 8
Lathe care and construction	Part 1
Lathe, size of	230
Lead, drilling of	87
Lead of thread	104
Lead screw	22
Lead screw bearing	23
Left hand threads	113-114
Lettered drills	225 table
Leveling the lathe	2
Line-shaft clutch	197-198
Locating centers	69-70
Lubricants, cutting	50
Lubrication	6-7 chart

—M—

Machine screw threads	139 table
Machining of various materials	Part 4
Machinists tables	Part 10
Mahogany (woodturning)	218
Major diameter	103

	Page		Page
Mandrel	81-82	Reaming operations	88
Mandrel press	82	Reeding	14
Maple (woodturning)	217	Reseating cutters, grinding of	177-178
Marblette, machining	66	Reverse gear box	23
Maudslay's lathe	IX Foreword	Reversing switch	174-175
Metal cutting theory	Part 2	Roughing tool bit	41
Metric system	223 tables	Routing	167
Metric threads		Rubber, hard, machining	66
119, 134 table, 141-142 table		Running in bearings	4
Mica undercutting with grinder	180-181		
Mica undercutting with under-		—S—	
cutting attachment	181-183	S. A. E. steels	52 table
Micarta, machining	66	S. A. E. steels, data and	
Milling attachment	166	descriptions	227-229
Milling attachment (boring operation)	93	S. A. E. thread, see National Fine	
Milling cutters	166	Sanding (woodturning)	215-216
Milling operations	166-171	Screw center	200, 213
Milling speeds	169	Screw cutting	Part 7
Minor diameter	103	Screw pitch gauge	107
Monel metal, machining	63	Serrating	14
Morse tapers	192, 194 table	Setover, tailstock	185, 188-189
Motor recommendations	3	Setting tool to work	42, 45-46
Mounting motor	3	Setting up lathe	1
Mounting work between centers	73-74	Shims, laminated	10
Multiple threads	119-122	Sizes of drills	225
		Skew chisel, large	204, 205
—N—		Skew chisel, small	214, 215
National Coarse thread	136 table	Sleeve and bushing assembly	96, 98
National Fine thread	137 table	Slipping teeth on spindle gear	121-122
National Form thread gauge	106	Spacer gear	98
National Form threads 106, 137-137 tables		Spark plug threads	138, 141 tables
National Special threads	138-139 tables	Special threads	125
Nickel, machining	63	Special tool shapes	41
Nickel silvers, machining	60	Speeds, drilling	87
Numbered drills	225 table	Speeds, milling	169
		Speeds, spindle	47, 230
—O—		Speeds, surface	49
Oak (woodturning)	217	Speeds, threading	110
Odd-pitch threads	132-133 table	Speeds, woodturning	216
Odd-pitch threads, formula for		Spindle bearings	8, 11
gear set-ups	155-156	Spindle end play adjustment	10
Oiling lathe	4, 6-7 chart	Spindle headstock	8
Overhang, avoiding	37	Spindle speeds (back-geared lathe) ..	47
		Spindle speeds (9-inch lathe)	230
—P—		Spindle speeds (Unit-Plan lathe) ..	230
Pine (woodturning)	217	Spoke-spacing	14
Pipe center	118	Spring-making	126
Pipe-type threads	117-118, 144 tables	Sprocket-spacing	14
Pitch diameter	103-104	Spur center	200, 201
Pitch of thread	104	Square threads	115-116, 143 table
Plaskon, machining	64	Squaring shaft end	167
Plastics, machining	64-66	Stainless steel, machining	56
Polishing	67	Steady rest	157-159
Poplar (woodturning)	217-218	Steady rest (woodturning)	261
Power feed mechanism	22	Steel, machining	50-53
Press, arbor or mandrel	82	Steel, drilling	87
Pulley clutch	197-198	Steel, complete table	52
Pyralin, machining	64	Steel, data and descriptions	227-229
		Steel, forged, machining	54
—Q—		Steel, tool, machining	53-54
Quadruple threads	121-122	Stove bolts	144 table
		Surface speeds	49 table
—R—		Surface speeds, milling	169 table
Rake angles	35, 42	Swing, lathe	230
Rake angles, boring	92		
Rake angles, threading	105	—T—	
Reamer grinding	178-180	Table boards	2
		Tables, machinists	Part 10
		Tailstock construction	24
		Tailstock setover	185, 188-189
		Tangents	186-187 table
		Tap drill sizes	136-144 tables
		Taper boring	190
		Taper cutting	183-195

	Page	Page
Taper cutting attachment	190-192	
Taper cutting tables	192-195	
Tenite, machining	64	
Textolite, machining	66	
Theory of metal cutting	Part 2	
Thread cutting	Part 7	
Acme	114-115, 143 table	
British standard	140 table	
fractional	138 table	
French standard	142 table	
internal	112-113	
International standard	141 table	
left hand	113-114	
Metric	119, 134 table, 141-142 table	
National Form	106, 136-137 table	
National Special	138-139 table	
odd pitch	132-133 table	
pipe type	117-118, 144 table	
precautions	111	
quadruple	121-122	
special	125	
square	115-116, 143 table	
Whitworth	117, 140 table	
Threading chart	97	
Threading dial	110-111	
Threading tool, circular	107	
Threading tools	104	
Thrust bearing adjustment	10	
Timken bearings	11	
Timken bearings, adjustment of	12	
Timken spindle, removing	16	
Tools, cutting	35-46	
boring	91-92	
edge of	33	
for armatures	183	
form-cutting	41	
grinding	37-40, Part 7	
roughing	41	
special	41	
threading	Part 7	
turning	38, 39	
woodturning	199-200	
Tool holders	37, 42-43	
Tool post grinder	171	
Tool rests for woodturning	200	
Tool steel, machining	53-54	
Trafford, machining	64	
Trueing armatures	182	
Trueing work in lathe	70, 75	
T-slots, milling	167	
Turret attachments	196-197	
Twist drills	83-85, 225 tables	
		—U—
Undercutting mica	180-183	
Unit Plan lathe, spindle speeds	230	
Universal chuck	76	
U. S. S. threads, see National Coarse		
Utility lathe, spindle speeds	230	
		—V—
Valve grinding	176-177	
Valve stem grinding	178	
Vee belts	16	
Vee cuts (woodturning)	207-208	
Vee threads	105	
Volumes, calculations	224 table	
		—W—
Walnut (woodturning)	218	
Weights and measures	222-223 tables	
White oak (woodturning)	217	
White pine (woodturning)	217	
Whitworth thread	117, 140 table	
Wire and sheet metal gauges	226 table	
Wire wrapping	126	
Wood and metal cutting, differences	30	
Woodruff key dimensions	170 table	
Woodruff keyway cutter	166	
Woodruff keyway slots	170 table	
Woods, types of	201, 217-218	
Woodturning operations	Part 9	
attachments	200	
cutting off	211-212	
facing	213-215	
finishing	215-216	
mounting work	201-202	
sizing grooves	206	
spindle speeds	216	
taking cut	202-203	
types of cuts	207-212, 214-215	
		—Y—
Yellow poplar (woodturning)	217-218	
		—Z—
Zamak parts	26-28	
Zamak parts, casting machine	28	

Acknowledgment

The drawing of Maudslay's lathe, page IX, Foreword, has been reprinted through courtesy of Popular Mechanics Magazine.